



## Annual Inspection Report Jan. Feb. 2024

Road	Section	Length verified	Length ft.	Width ft.	Sq ft	2/2024 ft cracking	%	Life	Recommend Date for resurface
<b>PAVEMENT</b>									
<b>Bywater Way</b>	BW-A	x	1344	14	18816	308	22.9%	2-4	2025
	BW-B	X	1340	14	18760	355	26.5%	2-4	2025
	BW-C	X	1358	12	16296	692	51.0%	1-2	2025
	BW-D	X	1073	12	12876	499	46.5%	1-2	2025
<b>N Bywater Way</b>	NBW-A	X	1690	12	20280	1020	60.4%	1-2	2025
	NBW-B	x	1606	12	19272	392	24.4%	1-2	2025
	NBW-C	x	1251	12	15012	431	34.5%	1-2	2025
<b>Olympic Ridge</b>	OR-A	X	1234	14	17276	12	1.0%	3-6	2030
	OR-B	x	1370	14	19180	620	45.3%	3-6	2030
	OR-C	x	890	15	13350	150	16.9%	3-6	2030
<b>Parkview</b>		x	800	12	9600	0	0.0%	3-7	2030
<b>Fern Gully</b>		x	711	10	7110	200	28.1%	1-2	2025
<b>Hidden springs</b>			1456	13.5	19656	469	32.2%	1-3	???
<b>TOTALS</b>			16123		207484	5148	31.9%		
<b>GRAVEL</b>									
<b>Bridgview</b>		X	1722	12.3	21180.6	Some pot holes, needs grade & shape			
<b>Hoodsview</b>		X	1023	14	14322	Some erosion, needs grade & shape			
<b>Shipview</b>		X	570	12	6840	Grade and Shape			
<b>Alpine</b>		X	1830	12	21960	Some pot holes, grade & shape			
<b>TOTALS</b>			5145		64302.6				